

DEALER EXECUTIVE SUMMARY

NEW VEHICLE DEMONSTRATION / DELIVERY HOLD – Safety Recall 15S21 – *Supplement #5*

Certain 2005-2006 Ford GT and 2005-2014 Mustang Vehicles
Driver Airbag Inflator or Driver Airbag Module Replacement

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

PROGRAM

Program Type	Safety
Stop Sale	No
Demonstration Hold	Yes
Delivery Hold	Yes
Program Expiration	None

PARTS & SERVICE

Parts Required	Yes
Parts Available	Yes
IDS Software Update Required	No
Interim Repair	Not applicable
Repair Universe/Percentage of vehicles expected to require a repair	100%
New FSA Special Service Tools Needed	No
Related Damage Provision	Yes, limits established
Labor Time	0.4 hours

CUSTOMER HANDLING

Towing Reimbursement	Follow Warranty & Policy Manual guidelines
Rental Assistance	No
Refunds Authorized	No
Special Handling	No

ADMINISTRATION

OASIS On	June 4, 2015
Owner Notification	<i>All remaining to be mailed the week of April 10, 2017</i>